Hampton) Inn & Suites

4220 West Bethel Avenue

Muncie Indiana, 47304

Phone: 765 288 8500

Fax: 765 28 8505

rax	<u> </u>
To: Fire Brevention & Bly Safety	From: Jan Jacob
Fax Number: 3172330307	
Phone Number: 3172322222	Date:
	cc:
For Review Pleas	Comment Please Reply
Comments:	.#
,	





Fire Prevention and Building Safety Commission
302west Washington Street, RM .W246
Indianapolis, IN 46204

Appeal for Variance

Sir/ Mm,

We had been inspected by the local Muncie Fire Department Inspector, Mr. Brad Riddle and have been sited on 3 different violations as listed in the inspection paper attached report. He has used citation based on state Codes 2003.

We have 9 hotels in Indiana and none of the hotels have been subjected to this type of inspection. I do also believe that not all the hotels in Muncie have the monitoring system which means that is discriminating to some hotels alone. The rectification of the violation would amount to almost \$4000, unexpected amount being spent from the budget. Not meeting budget for the quarter would also mean employees not getting their bonuses, which is really unfair to them.

I did talk to the Muncie inspector's office and he suggested the appeal was the right way to go about it and if the state grants the variance they were fine with this. He also said that the law book was so thick that they can come in every year and find at least 10 variances which they did not site last year. They would site things of importance only. If this 2003 code is so important to be fixed within 1 month of the citation, why it was not cited on the day we opened and 8 years of regular yearly state inspection.

for reservations please visit us at www.hampton.com or call 1.800.hampton

08\03\2012 10:34 \ \PE2888202 HAMPTONINN PAGE 02\08



I have already taken care of the

- 1. Combustible items like the hard plastic clipboards and replaced them with \$800 dollar metal cupboard in our mechanical room.
- 2. Knox Box (\$450) outside the building even though we have 2 people all the time in the building which is open throughout the year

As the inspector supervisor said they definitely can find some code in the code book which has been violated, I really find it discrimination to our hotel alone when I know there are plenty of hote apart from ours which this code has not been enforced. I am not trying to ridiculathe code or the inspectors enforcing the same, but just appealing to be fair to the small business operators and give a variance on the dates to enforce the codes instead of causing financial burden which they have not accounted for in their budgets.

I would appreciate if you could grant variant for the monitoring system till December when our budget for the next budget is set up. I shall try to take care of this before that if we are over in our budget any of the months before that.

In anticipation of fair response,

Sincerely,

Jim Jacob GM /Partner

Hampton Inn and suites

4220 West Bethel

Muncie, Indiana 47304

Phone: 7652888500/ 5743864463 fax 7652888505

OF official sponsor




for reservations please visit us at www.hampton.com of call 1.800.hampton



Muncie Fire Department

FIRE PREVENTION BUREAU



300 N High Street, Muncie, Indiana | 到7305 Telephone (765) 747-4876

Hampton Inn & Suites 4220 W Bethel Muncle, IN 47304

An inspection of your facility on revealed the violations listed below. Tuesday July 21, 2015

ORDER TO COMPLY: Since these conditions are contrary to law, you must correct them upon receipt of this notice. An inspection to determine compliance with this Notice will be conducted on or after:

Monday August 24, 2015.

Failure to remedy the violation(s) within the time period set forth above will result in the initiation of legal proceedings to restrain, conject or abate the violation(s). Such proceedings will require your appearance in count for a hearing on the matter. If a violation is found at that time, a fine of up to \$1000 will be imposed. The imposition of a penalty for a violation shall not excuse the violation nor permit it to continue. Each day a violation exists is considered a separate violation.

		4. 1.614
Violation Code	Article	Division Page Count
315.3.3 Equipment rooms.	675 IAC 22-2.5	i IFC 2014 0 1
Combustible material shall not be stored :	boiler rooms	, mechanical rooms or
electrical equipment rooms.		
Footnote: Remove combustibles from mechan	ital rooms as d	liscussed.
506.1 When required.	675IAC22-2.5-6	IFC 2014 0 1
Whenever the servicing fire department has	instituted a	key box emergency access
system, a key box compatible with that sy	stem shall be i	nstalled in an accessible
location if:		
(1) The building is protected with an aut	matic sprinkle	er system equipped with a
local or transmitted		
water-flow alarm, or		
(2) The building is provided with any fire	alarm system	equipped with an outside
audible/visual		
signaling device, or		
(3) The building is provided with any fire	elalarm system	where the alarm is
transmitted to an off-site	<u> </u>	
location, or to the fire alarm center for	the servicing	fire department.
		77.2
** Footnote: Knox box required for this faci.	Lucy. See 506.2	. Application left with
General Manager (Jim Jacob).		

07/22/2015 09:50


Page

1



Muncie Fire Mepartment

FIRE PREVENTION BUREAU



300 N High Street, Muncie, Indiana | 47305 Telephone (765) 747-4876

Hampton Inn & Suites 4220 W Bethel Muncie, IN 47304

506.2 Responsibility for key box.

Key boxes are to be provided by the building owner and shall contain such keys necessary to access all protected areas of the building. Multi-tenant buildings may share an owner-provided box, and the building owner shall assume responsibility for insuring that keys are propriate. Tenant-provided boxes may not be shared with any other tenant, and the tenant assumes responsibility for key updates for the subject tenant space.

Exception: Key boxes for apartment houses are not required to contain keys to individual apartment dwelling units.

675IAC22-2.5-6 IFC 2014

**Footmote: Reference only.

604.3.2 Written record.

Written records of the inspection, testing and maintenance of emergency and standby power systems shall include the date of service, name of the servicing technician, a summary of conditions noted and a detailed description of any conditions requiring correction and what corrective action was taken. Such records shall be kept on the premises served by the emergency or standby power system and be available for inspection by the fire code official.

Thus Breaker at 8 make once the light fallows

Footnote: Document annual emergency lighting tests (if done in house), providing

information listed above.

675IAC 22-2.5

IFC 2014

604.5.2 Power test.

For battery-powered emergency lighting, a wower test of the emergency lighting equipment shall be completed annually. The power test shall operate the emergency lighting for a minimum of 90 minutes and small remain sufficiently illuminated for the duration of the test.

Footnote: Annual 90 minute testing of exit and emergency lighting can be done by a fire protection service or performed in house as discussed. If performed in house testing shall be documented (see 60413.2).

675 IAC 22-2.5

907.15 /2003 Monitoring.

IFC 2003

Where required by this chapter or by local ordinance, an approved supervising station in accordance with NFPA 72 shall hinitor fire alarm systems.


07/22/2015 09:50

Page

te:01 910Z/Z0/80 7652888505



Muncie Fire Department



FIRE PREVENTION BUREAU

300 N High Street, Muncie, Indiana | 7305 Telephone (765) 747-4876

Hampton Inn & Suites 4220 W Bethel Muncie, IN 47304

* Footmote:												
Fire Code	when bui	.lding was	built	(build	din	compl	Leted	in 2	(800).	See	attache	ď
sheet with	h copies	of Indian	a Fire	Codes	£ø	fire	alarm	ь вуя	tem m	onito	ring.	
•												

NOTES COMMENTS

Quarterly fire drill due, last done in February 2015.

RIDDLE, BRAD

Inspector

Occupant/Owner

07/22/2015 09:50

3

Page

1998 Indiana Fire Code

1007:3.3.6 Monitoring

1007.3.3.6.1 General. When required by the building code or local ordinance, fire alarm systems shall be monitored by an approved central, proprietary or remote station service or a local alarm which gives audible and visual signals at a constantly attended location.

ಿ<u>2003 Indiana Fire Code</u>

Section 907 Fire Alarm and Detection Systems

907:15 Monitoring. Where required by this chapter or by local ordinance, an approved supervising station in accordance with NFPA 72 shall monitor fire alalim systems. (Eff. May 17, 2003)

2008 Indiana Fire Code

Section 907 Fire Alarm and Detection Systems

907.15 Monitoring. Where required by this chapter or by local ordinance, an approved supervising station in accordance with NFPA 72 shall monitor fire alarm systems. (Eff. June 16, 2008)

939 6183

APPEAL RIGHTS

Please be advised that if you desire administrative review of this Order, you must file a written petition for review with the: -

> Fire Prevention and Building Safety Commission 302 West Washington Street, Rm. W246 Indianapolis, IN 46204

FreMushal 317 2330307

You must identify the violations for which you seek review no later than 18 calendar days from the date of this Order unless such date is a Saturday, Sunday, legal holiday under state statute, or day that the Department of Homeland Security's offices are closed duling regular business hours, in which case the deadline would be the first calendar day thereafter that is not a Saturday, Sunday, legal holiday under state statute, or day that the Department of Homeland Security's office is closed during regular business hours. If you do so, your petition for review will be granted and an administrative proceeding will be conducted by an administrative law judge appointed by the Fire Prevention and Building Safety Commission. If you do not file a petition for review, this did der will be FINAL and you MUST comply with its requirements.

Please be further advised that you may request an opportunity to informally discuss this Order prior to filing a petition for review. Such informal discussion, or Mequest therefor, does not extend the deadline for filing a petition for review and, therefore, any request for an informal discussion should be made promptly, preferably by telephone (317 232-2222), upoh receipt of this Order.

Bux Sectors